



14 July 1998

2600 Bull Street Columbia, SC 29201-1708

COMMISSIONER:

Douglas E. Bryant

Department of the Navy Southern Division NFEC

ROARD: John H. Burriss

P.O. Box 190010

Re:

Chairman

North Charleston, SC 29419-9010

William M. Hull, Jr., MD

Vice Chairman

Attn: Mr. Gabriel Magwood

Roger Leaks, Jr. Secretary

Mark B. Kent

Underground Storage Tank Assessment Report dated 22 May 1998

Cvndi C. Mosteller

Ouarters "R" Housing (Site Identification # 15405-General File) Charleston Naval Complex/Charleston Naval Base

Brian K. Smith

Charleston, SC

Rodney L. Grandy

Charleston County

Dear Mr. Magwood:

The author has completed technical review of the referenced document. As submitted, the report provides a narrative describing closure activities and analytical results of environmental sampling to determine if releases have occurred as a result of operation of the referenced vessel and/or associated piping system. The analytical results provided indicate reportable concentrations of BTEX and PAH compounds were detected in soil grab samples obtained from the UST excavation and the piping run excavation. The reported concentrations are below levels proposed in the SCAP (Soil Corrective Action Plan, amended July 1997). Based on review of the employed closure activities and sampling results it appears that no additional endeavors for remedial actions and/or contaminant characterization is warranted for Quarters "R" Housing at this time. Please be aware this statement pertains only to the portion of the facility addressed in the referenced document and does not apply to other areas of the facility and/or any other potential regulatory violations. The Department retains the authority to request additional assessments and/or remedial endeavors, as appropriate, if future conditions or information warrant and are deemed necessary.

Should you have any questions please contact me at (803) 734-5328.

Sincerely,

Paul L. Bristol, Hydrogeologist

Groundwater Quality Section

Bureau of Water

Tom Knight, Manager

Groundwater Quality Section

Bureau of Water

CC:

Trident District EQC